


QST 18
001 PT 0007


L1 - 3A
L2 - 3A
L3 - 3A
L4 - 4A



GENERAL	ETHNOLOGIA	SCOLTA	UBUNA	CHATA	SCOLTA	AUTOMATE	AUTOMATE	AUTOM.	AUTOMATE
4C40	4C25	2C16	2C16	2C16	2C16	2C25	2C25	2C25	2C25
6kA	6kA	4,5kA	4,5	4,5	4,5	6	6	6	6
0,3	0,3	0,03	0,03	0,03	0,03	0,03	0,03	0,03	0,03
AS	AS	AC	AC	AC	AC	AC	AC	AC	AC
FG17	FG17	FG17	FG17	PG17	FG17	FG17	FG17	FG17	FG17
4 mm ²	4 mm ²	4 mm ²	4	4	4	6	6	6	6

Q. D. T. 18

USCETA UPS
 L1 11A
 L2 4A
 L3 2A
 N 8A



Z10 Z11 Z12

UPS SPYLOG PIRESE PIRESE ACETABOLAE
 001/PT/1077 CONDUSOIO UPS 001PT 1084

4C25	ZC20	ZC16
6kA	6kA	0kA
0,03	0,03	0,03
AC	AC	AC
FG	FG	FG
2,5 mm ²	4 mm ²	2,5